

1560 meter calibration method scales

In the case of the instrument off, press and hold the left button to
【set button】 the right hand turn on the instrument 【power switch】.
2 seconds left. Instrument displays **CAL** to enter the school scale.
CAL1 maximum capacity set 100KG
CAL2 minimum capacity set 0.1KG
CAL3 entered in the empty scale 10KG
In the empty scale CAL4 Press Set (zero calibration)
333222111
CAL5 load 10KG press Set objects (physical calibration)
333222111
End calibration instrument display END, press the Set button to
launch the calibration.

1560 仪表校秤方法

在仪表关闭的情况下,左手按住设定键,右手打开仪表电源开关.左手保持 2 秒.
仪表显示 CAL 为进入校秤.

CAL1	最大秤量设定	100KG
CAL2	最小秤量设定	0.1KG
CAL3	在空秤下输入	10KG
CAL4	在空秤下按设定键(零点标定)	
	333	222 111
CAL5	加载 10KG 物体按设定键(实物标定)	
	333	222 111

标定结束仪表显示 END,按下设定键推出标定.